

Status of bridge inspection 1

(1) Inspection Status

• The integrity of bridges is confirmed through patrol inspections and periodic inspections conducted once every five years.










Status of bridge inspection 2


(2) Inspection status using large special vehicles and new technologies (National)

- •Bridges on national highways under direct control are often large- span bridges, and regular inspections are conducted using large special vehicles.
- •We conduct bridge inspections utilizing drone technology and other methods, thereby improving the efficiency of inspection and documentation tasks.





Inspecting damage to elevated bridges through close-range visual inspection



Utilization of drones and image analysis technology



Detection of Floating Objects
Using Mobile Seismic Wave
Survey Method



Bridge Repair and Reinforcement Case Studies 1

(1) National Highway Bridge

• Through regular inspections, we detect damage early and implement planned countermeasures.

National Route 329 AneBridge (Ogimi Village) Built in 1984

[Damage Cases]







[Countermeasure Examples]


Salt damage caused peeling of the main girder and exposure of reinforcing bars.

Electrical corrosion protection

National Route 506 Yamakawa Overpass (Haebaru Town) Built in 1999

[Damage Cases]







Corrosion of bolts and corner areas

Repainting of steel girders, replacement of bolts

National Route 58 Yamashita kinohana Overpass (Naha City) Built in 1983

[Damage Cases]



Cracking at the main girder ends caused by alkali-aggregate reaction

Countermeasure Examples



Protective coating of the main girder

Bridge Repair and Reinforcement Case Studies 2

(2) Prefectural road bridge

Even in the prefecture, damage is detected early through regular inspections, and measures are implemented in a planned manner.

Prefectural Route 14 Tahara Bridge (Nago City) Built in 1976

[Damage Cases]



Steel corrosion caused by salt damage, lack of an anti-collapse system

[Damage Cases]



Cracks and delamination have occurred in the concrete deck due to salt damage.

(Damage Cases)



Corrosion of bolts and corner areas

【Countermeasure Examples】



Repainting, Installation of a fall-prevention system


[Countermeasure Examples]



は A Manual A Manual

Crack Injection

【Countermeasure Examples】



Bolt replacement, repainting